

# SHIMS? Make Mine Laminated!

by Russell R. Radant  
Chief Engineer  
Spirol International Corporation

*Laminated shims make life easier for designers and machine operators, as long as they're properly specified.*

It's often quicker and less expensive to use a shim, a thin piece of metal or composite, to level a machine tool or make components fit together than grinding and machining to make the same mechanical adjustments. Shims act like those folded pieces of paper people place under table legs to prevent the table from wobbling. They are also used to quell vibrations and silence noisy equipment. But laminated shims are more versatile and economical than slivers of paper or machined wedges.

## Laminated Shims

Laminated shims have peelable layers of metal or composite which are removed until the shim has the proper thickness. Adjusting them is as easy as peeling off laminations with a knife, or in the case of some materials, using no tool at all. They are built up from layers of precision-gauge metal foil or composites. Layers are bonded into a rigid structure that appears and functions as a solid sheet or plate. The finished shims withstand reasonable handling, including shearing and machining.

Laminated shims are produced by surface-bonding layers of precision-metal foils or composite films and resin adhesive into sheets. The foils can be aluminum, stainless steel, carbon steel, and brass, among others. Final shims range from 0.006 to 0.250 in. thick. The bond is made by heat and pressure, which hardens and reduces the resin to a point where it is almost undetectable. At temperatures above approximately 300°F (150°C), however, the bonding agent may deteriorate and there will be a negligible loss of total thickness. But even heating the resin to above 446°F does not influence the performance of the shim.



Laminated shims come in a variety of materials, shapes and sizes.



Laminated shims can be peeled down, layer by layer, until they are the proper thickness.

## Shim Considerations

Designers should know the forces that will be placed on the laminated shim before choosing a shim material. And shim faces should not be exposed to friction-causing motions unless the shim has a PTFE treatment. Otherwise, the shim could delaminate. However, if parts have location holes, the only forces will be those exerted by the tightening of screws. In this case there are no limitations on using laminated shims. Laminated shims should be machined rather than stamped. Machining leaves clean edges that make shims easier to peel. Machining also prevents burrs from forming when peeling layers away. The burrs are a by-product of die rolls and stamping.

Laminated shims can be partially solid and partially laminated. This type of shim is either half-solid or three-quarter solid, depending on the ratio of solid section to total thickness. Standard thicknesses for the solid part are 0.062, 0.094, and 0.125 in. Semisolid shims are used to add rigidity to a design, accommodate a bearing surface on one side of the shim, meet requirements for a thick shim that will have minimal adjustments made to it, and to lower costs.

There are some size restrictions on laminated shims. For example, brass laminated shims larger than 12-in. in diameter must be made in sections. As a general rule of thumb, all thicknesses should never be less than three times the total material thickness. Edges of laminated shims should not be rounded, and deburring laminated shims may make them difficult to peel.



## Why Use Shims?

There are three basic reasons for designing shims into assemblies and devices:

**Tolerance Compensation.** Shims eliminate the time and cost of putting precision tolerances on mating components. They also compensate for accumulated tolerances during assembly. It is better to design in a shim than to discover later you need one at the assembly stage.

**Precision Alignment.** Shims align parallel and angular surfaces when interfacing elements must be coupled.

**Wear Compensation.** Shims compensate for wear and are often designed to be the sacrificial component so the basic equipment retains its original accuracy.

## Where Laminated Shims are Applied

- Where rotating shafts and sliding or stationary surfaces must be parallel
- Where endplay is unacceptable
- Where stacked or accumulated tolerances are difficult to control
- Where rotating wear, sliding wear, or other forces change an assembly's or component's dimensions.

## Advantages of Laminated Shims

- Reduce assembly time
- Dimensional accuracy without machining components
- Quick production line adjustments and field repairs
- No need for grinding
- Minimize costs and maximize precision with fewer items to inventory



## Selecting the Right Laminate Material

Material	Pressure Resistance (psi)
Aluminum	14,223
Brass	64,004
Stainless steel	99,562
Carbon steel	120,897

If the application is:

- Less than 300°F with no pressure: use aluminum.
- Less than 300°F with pressure: any material listed can be used.
- Greater than 300°F with or without pressure: use brass, stainless steel, or carbon steel.

**U.S.A.** **Spirol International Corporation**  
30 Rock Avenue  
Danielson, Connecticut 06239  
Tel. +1 860.774.8571  
Fax. +1 860.774.2048  
(US Distributors: Fax. +1 860.774.0487)

**Spirol International Corporation  
Shim Division**  
321 Remington Road  
Stow, Ohio 44224  
Tel. +1 330.920.3655  
Fax. +1 330.920.3659

**Spirol West Inc.**  
1950 Compton Avenue, Unit 111  
Corona, California 92881-6471  
Tel. +1 951.273.5900  
Fax. +1 951.273.5907

**Canada** **Spirol Industries, Ltd.**  
3103 St. Etienne Boulevard  
Windsor, Ontario  
Canada N8W 5B1  
Tel. +1 519.974.3334  
Fax. +1 519.974.6550

**Mexico** **Spirol México, S.A. de C.V.**  
Carretera a Laredo KM 16.5 Interior E  
Col. Moisés Saenz  
Apodaca, N.L. 66613 México  
ó Apdo. Postal 151 de Apodaca, N.L.  
Tel. +52 81 8385 4390  
Fax. +52 81 8385 4391

**Europe** **Spirol Industries Ltd.**  
17 Princewood Road  
Corby, Northants  
NN17 4ET United Kingdom  
Tel. +44 1536 444800  
Fax. +44 1536 203415  
(UK Distributors: Tel. 0800 3890034)

**Spirol SAS**  
Cité de l'Automobile ZAC Croix Blandin  
18 Rue Léna Bernstein  
51100 Reims  
France  
Tel. +33 3 26 36 31 42  
Fax. +33 3 26 09 19 76

**Spirol GmbH**  
Briener Strasse 9  
80333 Munich  
Germany  
Tel. +49 931 454 670 74  
Fax. +49 931 454 670 75

**Spirol SAS en España**  
08940 Cornellà de Llobregat  
Barcelona  
Spain  
Tel. +34 93 193 05 32  
Fax. +34 93 193 25 43

**Spirol S.A.S., organizační složka**  
Sokola Tůmy 743/16  
Ostrava-Mříánské Hory 70900  
Czech Republic  
Tel/Fax. +420 417 537 979

**Asia Pacific** **Spirol International Engineered  
Fastener Trading Co. Ltd.**  
No. 11 Xi Ya Rd. North  
Section A, 1F, Building 14  
Wai Gao Qiao Free Trade Zone  
Shanghai, China 200131  
Tel. +86 21 5046-1451/1452  
Fax. +86 21 5046-1540

**e-mail: [info@spirol.com](mailto:info@spirol.com)**

**SPIROL.com**

ISO/TS 16949:2009 Certified  
ISO 9001:2008 Certified

© 2003-2012 Spirol International Corporation

No part of this publication may be reproduced or transmitted in any form or by any means, electronically or mechanically, except as permitted by law, without written permission from Spirol International Corporation.